
Fw: File Number: 2023-CSD-0002 Arborists Reports 3803 NE 155th

From David Greetham <dgreetham@cityofflp.gov>

Date Thu 10/17/2024 5:09 PM

To Drue Epping <depping@cityofflp.gov>


 1 attachments (1 MB)

image.png;

Part two...

David Greetham | Temporary Senior Planner

City of Lake Forest Park

17425 Ballinger Way NE | 360-265-2441

www.cityofflp.gov

From: Paula Goode <paula.m.goode@gmail.com>

Sent: Thursday, October 17, 2024 4:48 PM

To: David Greetham <dgreetham@cityofflp.gov>

Subject: Re: File Number: 2023-CSD-0002 Arborists Reports 3803 NE 155th

Trying not to overwhelm you!

On Thu, Oct 17, 2024, 4:38 PM David Greetham <dgreetham@cityofflp.gov> wrote:

Hello Paula,

Thank you for the additional comments (including attachments); they are being shared with the City Arborist for consideration during project review.

Please don't hesitate to contact me should you have any questions.

Best,

David Greetham | Temporary Senior Planner

[City of Lake Forest Park](#)

[17425 Ballinger Way NE](#) | 360-265-2441

www.cityofflp.gov

From: Paula Goode <paula.m.goode@gmail.com>

Sent: Thursday, October 17, 2024 1:01 PM

To: David Greetham <dgreetham@cityoflfp.gov>; Mark Hofman <mhofman@cityoflfp.gov>

Subject: Fwd: File Number: 2023-CSD-0002 Arborists Reports 3803 NE 155th

Hello,


Another issue is the Exceptional Cedar tree that they want to remove that has its root system below my home, see screen snapshot of Page 1 of Plans. Removal of this tree would endanger the safety and stability of the slope as well as my residence. The reason the tree is at such an angle is due to the slide on the adjacent property, 3829 NE 155th , in 1997. My arborist reviewed my exceptional cedar very close to this one, and indicated that even though it is slanted at the bottom, it has since recovered because the upper branches are now vertical. The root system of the tree they want to remove helps to stabilize our slope and this is critical to our safety.

The LFP Consultant indicated that the building plan be revised to avoid this tree, however it does not look as though this has been completed.

Attached are the two arborists' reports, one from their arborist, one from LFP arborist consultant.

Thank you for your assistance in this matter,

Paula Goode

image.png